

BUILDING SAFETY CERTIFICATE

No. 02/Lamp

Dated: 15/6/23

Certified that the existing building **Don Bosco Academy** (name of the building or premises) at **Budwar Road Lalitpur** (address) comprised of **zero** basement(s) and **Three floor** (upper floors) owned/occupied by have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **PWD** (Name of Department/Govt.) on....15/6/23....(date of inspection) in the presence of **Fr. Peter Sylvester budwar road lalitpur 284403** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy up to classes XII (X/XII) with effect from....15/6/23....for a period of.....03.....years in accordance with rule and subject to compliance of the specific conditions as appended.

1. The building should be used only for school purposes.
2. Regular / Periodic maintenance should be done like repair of joints, painting, waterproofing etc.
3. Building should be inspected during rainy season for any leakage and clogging of pipes so that any adverse conditions can be avoided.

Issued on....15/6/23....at....Lalitpur....by

Signature with Seal: _____ NAVNEET SINGH RAJPUT

Name: _____ सहायक अभियन्ता प्रा० ख० लो० वि० वि०

Designation: _____ ललितपुर

Name & Address of Department/Office: _____

L. By...
PRINCIPAL
DON BOSCO ACADEMY
LALITPUR (U.P.)

[Signature]
MANAGER
DON BOSCO ACADEMY
LALITPUR (U.P.)